

VAN'S AIRCRAFT, INC.

14401 NE Keil Road, Aurora, Oregon 97002 • USA
PHONE 503-678-6545 • FAX 503-678-6560
INTERNET www.vansaircraft.com • E-MAIL info@vansaircraft.com

SERVICE BULLETIN NUMBER: 04-3-1

DATE ISSUED: March 19, 2004

APPLICATION: Electric flap drive motors.

SUBJECT: Multiple holes in attach lug.

BACKGROUND AND INTRODUCTION:

The manufacturer of the motor/drive assembly used in all RV electric flap installations is recalling some flap motor/flap drive assemblies. The actuator arms of these components have been drilled with two holes at right angles, instead of the intended single hole (see illustration).

RECOMMENDATIONS:

Although no service difficulties arising from this aspect of the electric flap installation have ever been reported to Van's Aircraft, Inc., we are requesting the return of all such electric flap motor/drive assemblies.

